

## **20.30.4.147 Changelog**

# Table of Contents

<b>1 Firmware Version .....</b>	<b>3</b>
<b>2 Previous version.....</b>	<b>4</b>
<b>3 Release Date .....</b>	<b>5</b>
<b>4 Supported SmartPlus Version.....</b>	<b>6</b>
<b>5 New Features .....</b>	<b>7</b>
<b>6 Fixed Bugs .....</b>	<b>8</b>
<b>7 Known Bugs .....</b>	<b>9</b>

# 1 Firmware Version

20.30.4.147

## **2 Previous version**

20.30.4.141

### **3 Release Date**

2021.08.19

## **4 Supported SmartPlus Version**

Cloud-5.2

## 5 New Features

1. Optimized fluency of sound streams(R20K) in low memory scenarios.
2. Lighttpd, openssl, curl library upgrade (security related).
3. Disable Video call logic in account mode.

## 6 Fixed Bugs

1. The abnormal CPU usage of the multimedia process after a call.
2. Keytone thread not being destroyed causing thread leak.
3. Potential deadlock in JPEG encoding process.



## 7 Known Bugs

None